

Utfärdare  
Issued by **AFTPT Bertil Gustafsson**Datum  
Date **April 1979**

Distr.

**NOISE FROM REAR SHOCK ABSORBER**

In the event of noise from the rear shock absorbers first check that the lower mounting is properly tightened.

Torque, rear shock absorber, lower mounting	95 ± 5 Nm (70 ± 4 ft.lb., 9.5 ± 0.5 kpm)
---	--

-----

Delgivet den Informed							
Sign.							

Personbilsdivisionen  
Saab Car DivisionPostadress  
611 81 NYKÖPINGPostal Address  
S-611 81 NYKÖPING  
SwedenTel.  
Nat. 0155/807 00  
Int. +46 155 807 00Telegram Address  
saabcarTelex  
640 18 saabcar s



