

Date MARCH 1979

Filing No. 6/01/79

Distribution No. FULL NETWORK DISTRIBUTION

MODEL 900

Subject: Power Steering Fluid

In the event of having to replace all the power steering oil after overhaul or replacement of any of the components, it is essential to use a particular type of power steering oil specially developed for this purpose. This is Texaco 4634. This is available through our Parts Department and it is Type 45 part No. 3009800.

One bottle of 75 cm³ will be sent to you as automatic issue, therefore no parts orders are required for this initial issue. However, to obtain replacement stock, normal parts order procedures must be used.

For topping-up purposes it is permissible to use automatic transmission fluid.

WARNING

The oil pump will be damaged if dirt enters with the Hydraulic Fluid during topping-up or re-filling.

